# **Borth Coastal Protection Scheme - Weekly Report**

Week 61 – ending 11<sup>th</sup> March

ECC PM:AtkinsRob MorganContractor:BAM NuttallRay JonesCDM coordinatorFaithful and GouldMartin ClarkSite SupervisorRoyal HaskoningAlice Johnson

### **Planned Activities**

Area		Description	Completion	
Site Comp	ound	Completed. Main number is 01970 871 834.	100%	
Beach Access North		North Access is complete Some replacement and rock fragments remain. No further work.	100% place 80% tidy up	
Beach Acc	ess South	Southern access is complete.	100%	
Groyne 1		Groyne 1 is complete.	100%	
Groyne 2		Groyne 2 is complete	100%	
Breakwate	r 1	No further work on Breakwater 1 done.	19% top	
Breakwate	er 2	Breakwater 2 is complete.	100% k removed. 100% build	
Temporary Causeway		Temporary causeway is complete. South link removed.	100% build ~60% removal	
North Ree	f	Work has continued to clear broken rock and place the primary armour on the reef.	98% bedding 100% core 80% top	
South Reef		South Reef is complete	100% bedding 100% core 100% top	
Shingle Material	Nourishment	Shingle deliveries are now complete.	100%	
Shingle Placement	Nourishment	The replacement material is now complete. The main beach up to behind breakwater 1 and been placed to profile.	93%	
Other		A maritime exclusion zone is now in place around the reef and causeway; the reefs are now marked by the permanent west cardinal.	-	

## **Weather and Tidal Conditions**

Spring tides and good weather.

#### **Plant on Site**

- 1Nr. Bulldozer (used for beach work)
- 1Nr. Tele-handler and bowser all week
- 3Nr. 450 tracked excavator with grabs
- 1Nr 340 Excavator with griddle bucket
- 3Nr. 35t dumper truck (1 on standby)

### **People on Site**

- 6Nr. Bam Staff and Support
- 7Nr. Labour
- 5Nr. Plant operators

### Material approval and delivery

- Rock deliveries complete for the moment.
- Some broken rock to dispose.
- Further material to retrieve form causeway.

Туре	E - Rep.	C1 - Natural	5-100kg	0.3-1t Rock	0.5-1t	3-6t Rock	6-10t
			Stone		Rock		Rock (Nr.)
Total to week	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Previously	122,699.91	54,667.78	13,419.71	21,916.88	7,755.28	26,680.70	47,915.60
Total to date (14.2.12)	122,699.91	54,667.78	13,419.71	21,916.88	7,755.28	26,680.70	47,915.60
QS Total (22.2.11)	123,940	52,130	15,151	22,202	7,806	25,241	48,274

NB. This is an approximate table and checked tonnages are held by QS.

#### **Planned Activities Next Week**

- Place rocks on north reef.
- Continue work on breakwater 1
- Carry out slipway rock bund.

# To do before completion

- Shingle Nourishment top up behind breakwater 1
- Remove main causeway,
- Remove working stockpiles, sort out material
- Profile remaining beach nourishment
- Complete North Access
- Reinstate South Access
- Remove machines and cabins
- Snagging

### **Public Relations**

 Opening ceremony on Thursday and a good turn out form the local community, school and dignitaries.