Borth Coastal Protection Scheme Phase 2 – Site Supervisors Weekly Report

Week 10 – ending 3rd August

ECC PM:	Atkins	Rob Morgan
Contractor:	BAM Nuttall	Ray Jones
CDM Co-ordinator:	Royal HaskoningDHV	Steve Vernon
Site Supervisor:	Royal HaskoningDHV	David Cramp

Planned Activities

Area	Description	Completion
Site Compound	Compound set-up was complete.	100%
Beach Access and	Beach access area is complete and rock deliveries	15%
Rock Stockpile	have commenced. Type 1 and Type 3 rock deliveries	
	are received daily.	
Breakwater 1	Work yet to commence	0%
Breakwater 2	Work yet to commence	0%
Breakwater 3	Work yet to commence	0%
Groyne 1	Work yet to commence	0%
Groyne 2	Work yet to commence	0%
Groyne 3	Work yet to commence	0%
Beach Nourishment (Phase 2)	Work yet to commence	0%
Beach Nourishment (Phase 1)	Work has been completed on re-profiling Phase 1 to +4.5m OD based on PMI 4. This released approximately 860m3 of shingle for re-use in Phase 2 nourishment.	100%

Weather and Tidal Conditions

• Calm weather throughout the week with sunny spells.

Plant on Site

- 1Nr. P65 Dozer Not Used
- 1Nr. 45t tracked excavator with grab
- 3Nr. 45t tracked excavator with bucket (2 Not Used)
- 2Nr. 35t dumper truck Not Used

People on Site

- 4Nr. BAM Staff (Site)
- 3Nr. BAM Staff (Office)
- 2Nr. Plant Operatives
- 4Nr. Labour

Material Approval and Delivery

• Material deliveries continued from Bolton Hill and Garnwen Quarries in Pembrokeshire, and Tonfanau Quarry in Tywyn.

Туре	Type 1 (3-6t)	Type 3 (300-1000kg)	75/40	Type A (Shingle)	Type B (Shingle Backfill)	Type C (40mm)
Total to week	1780.45	1808.96	0	0	0	0
Previously	10880.83	7178.63	884.01	0	0	0
Total to date (01.08.14)	12661.28	8987.59	884.01	0	0	0
QS Total	-	-	-	-	-	-

Planned Activities Next Week

- Rock deliveries will continue.
- Removal of timber groynes will commence at the northern end of the beach by the golf course.
- Construction will commence on Breakwater 3 and Groyne 2 at the northern end of the beach.